i ,

•

| DEPARTMENT: | 101-512-445 | |
|-------------------|---------------------------------------|--|
| VENDOR: | Team Solutions, Inc | |
| PO # | N/A | |
| PO DATE: | | |
| INV DATE: | 11/15/2021 | |
| APPROVAL REQUIRED | DATE APPROVED: | |
| EXPLANATION: | PO was not requested prior to repairs | |

•

.

١

.



RECEIVED

JUNTY

NOV 1 6 2021

INVOICE

16441

Navarro County Sheriff Office 312 W 2nd Ave Corsicana, TX 75110

0

W-S-4516 WDJTOR'S OFF **Navarro County Sheriff Office** 312 W 2nd Ave Corsicana, TX 75110

NAVANCE

T.E.A.M. Solutions, Inc. 2025 South 12th Street Waco, TX 76706 (254) 756-6900

| ORDERED BY | CUSTOMER PO | ORDER NUMBER | INVOICE DATE | DUE DATE | PAGE |
|------------|-------------|--------------|--------------|------------|------|
| Brad | | 21111101 | 11/15/2021 | 11/15/2021 | 1 |

DESCRIPTION SC@ AC-05 is heating and cooling at the same time.

RESOLUTION 11/11/21 - Logged in remotely to see if I could fix anything without a site visit. Found issue with graphics that was repaired under warranty. Determined the programming was working properly and I would need to go onsite to work on AC-05. Also saw that AC-01 was calling for the fan to run but the controller did not receive a signal confirming it was running. Turned on the cooling output and the unit did not appear to be cooling so I would need to troubleshoot it on site as well. Arrived on site and met with Brad. Went to control panel for AC's 1-5 and inspected module for AC-05. Found the module output for the compressor was damaged and the module would need to be replaced. Disconnected the terminal for the compressor and reinstalled the module so it could continue to heat and run the fan as needed. Showed Brad how to replace the module once I had one shipped to him. Moved onto AC-01 and found the controller was not receiving 24v from the unit. Traced wiring to relay panel and had no voltage from the unit there either. We went to the roof and found the disconnect for AC-01 was turned off. Brad contacted the mechanical contractor to see if it was okay to turn it back on and he said it was. Turned on the disconnect and verified the unit was operating properly. -CC

| ITEM NO | QUANTITY | DESCRIPTION | UNIT PRICE | EXTENDED |
|----------------|----------|-----------------|------------|----------|
| T 999999999900 | 2.0hr | 24-TRVL-00-1REG | 100.00 | 200.00* |
| T 999999999927 | 2.0hr | 13-TECH-00-1REG | 150.00 | 300.00* |
| T 000000000927 | 1 | 375617 | 275.50 | 275.50* |

^{*} means item is non-taxable

TOTAL AMOUNT

775.50

Monio Steward

Desc: <u>Unit AC-05</u> - Replaces Max Unit ACOS -

PO#:MA____ Invoice#: 1644

Vendor#:593



NAVARRO COUNTY AUDITOR'S OFFICE

300 W 3rd Ave, Suite 6 Corsicana, Texas 75110 e-mail: auditor@navarrocounty.org

Natalie Robinson, First Assistant, Kaye Martin, Assistant Lisa Clay, Assistant Patty Wells, Assistant Jan Wise, Administrative Assistant

Terri Gillen, County Auditor

Phone: (903) 654-3095

Fax: (903) 654-3097

INTEROFFICE MEMO

| The att | ached item is being returned for the following reasons: | | | |
|---------|---|--|--|--|
| X | Item incurred before purchase order issued | | | |
| 0 | Purchase order number is inconsistent with invoice | | | |
| ۵ | Amount billed does not match the purchase order | | | |
| ٥ | Vendor on purchase order does not match invoice | | | |
| 0 | Insufficient documentation to process payment | | | |
| ٥ | Signature or date not present | | | |
| 0 | Budget Account Number (Line Item) is missing – Acct # | | | |
| | Insufficient budget | | | |
| | Payment Request inconsistent with County Policy | | | |
| ٥ | Other | | | |
| This no | provide the additional documentation or explanation necessary to process this payment request. police must remain attached to the payment request. | | | |
| that th | epartment Head or Elected or Appointed Official must sign this form confirming notification e Navarro County Purchasing Policy was not followed on this purchase. RECEIVED steward 11/17/202) Date NOV 1 7 2021 | | | |

Revised 06/24/19

NAVARRO COUNTY AUDITOR'S OFFICE