

## RECEIVED JAN 2/ 2025 NAVARRO COUNTY AUDITOR'S OFFICE

## NAVARRO COUNTY AUDITOR'S OFFICE

300 W 3" Ave., Suite 4 Corsicana, TX 75110

Natalie Robinson, First-Assistant Patty Mosley, Assistant Lisa Clay, Assistant Vicki Lewis, Assistant Krystal McCollum, Assistant Kari Davis, Purchasing Assistant

Terri Gillen, County Auditor Phone: (903) 654-3095

e-mail: auditor@navarrocounty.org

Fax: (903) 654-3097

## **INTEROFFICE MEMO**

The attached item is being returned for the following reasons:

- K Item incurred before purchase order issued
- Purchase order number is inconsistent with invoice
- Amount billed does not match the purchase order
- Vendor on purchase order does not match invoice
- Insufficient documentation to process payment
- Signature or date not present
- System shows invoice paid
- Budget Account Number (Line Item) is missing Acct #
- Insufficient budget in Line Item
- Payment Request inconsistent with County Policy
- Other

Please provide the additional documentation or explanation necessary to process this payment request. This notice must remain attached to the payment request.

Additional explanation:

The Department Head or Elected or Appointed Official must sign this form confirming notification that the Navarro County Purchasing Policy was not followed on this purchase,

Uno Cindens

Signature

1/28/25

REC BROWN JAN Istributors JAN NAVAR AUDITO	EIVED 2 / 2025 RO COUNTY DR'S OFFICE	Invoice Number: Invoice Date:	Invoice Page: 1 SV-INV057296 1/23/2025
Bill To: Navarro County Jail Navarro County Jail 312 W 2nds Avenue Corsicana, TX 75110 USA	Debit: Desc: PO#:	Ship To: Navarro County Ja 300 West 2nd Corsicana, TX 7511 USA	
Due Date 2/22/2025 Terms Payment 3	Invoice#: /endor#: 0 days after invoice date	Customer ID P.O. Number P.O. Date Our Order No. SalesPerson	EBD-51874 1/14/2025 SVO085550 Jack Johnson

## **Repair Description**

Return to repair W#3, installed new Control, Door gasket. Once complete tested good!. D#3 - Repaired, replaced Old lint Screen cleaned and tested. W#1-Checked, Diagnosed, found bad Cold Valve, ordered new Valve. D#2 - Replaced damage Start Button.Customer need chemical pumps addressed and update. Replace two squeeze tubes provide by customer.

Model No.	Serial No.	Machine Description	
	2420462M18	Rmg070p1102 - W#3	
FWS-60 TP2 HW	8102279893	200 G-FORCE FAGOR WASHER	
	1609058945	KT075NQTB1 - D#3	
	1609058944	KT075NQTB1 - D#2	

Item/Descriptio	n	Unit	Order Qty	Quantity	 <b>Unit Price</b>	<b>Total Price</b>
PRT-FREIGHT	Parts-Freight	Each	1	1	36.95	36.95
CG- ALSM400522	ASSY LINT SCREEN ST 73	Each	1	1	72.40	72.40
CG-540591	PROCESSOR BOARD, MG623/ RMG055 LOGI PRO	Each	1	1	714.13	714.13
CG-563346	DOOR GASKET65SHA - MS-623 RMG055 (REPLACES #359828)	Each	1	1	166.28	166.28
CG- ALS70455101	SWITCH, ROCKER (DPST OFF-(ON)) GREEN	Each	1	1	35.26	35.26
SV-JACJOH	Jack Johnson Lbr Track	Hour	0.71053	0.71053		
SV-JACJOH	Jack Johnson Lbr Track	Hour	0.71053	0.71053		
SV-JACJOH	Jack Johnson Lbr Track	Hour	0.35526	0.35526		
SV-JACJOH	Jack Johnson Lbr Track	Hour	0.47368	0.47368		
SRV-LABOR	Service Call Labor	Each	2.5	2.5	145.00	362.50
SRV-FLATCHG	Service-Service Charge	Each	1	1		000100



Amount Subject to Sales Tax

Amount Exempt from Sales Tax

989.76 397.76



Subtotal:	1,387.52		
al Sales Tax:	81.64		

Total: 1,469.16

Click Here to Pay